

CP-60M 60MHz示波器測棒

60MHz X1 & X10 切換


接地夾 測試鉤 絕緣套 標示環 調整棒




X1X10 切換鍵

規格表


頻寬	60MHz
上升時間	5.8ns
衰減係數	X1 & X10
輸入電阻	X1: 1MΩ±2% X10: 10MΩ±2%
輸入電容	X1: 70pF~120pF X10: 14pF~18pF
最大額定 輸入電壓	X1: 150Vrms CATII X10: 300Vrms CATII
補償範圍	15~45pF
使用環境	0~50°C, 0~80%RH
存儲環境	-20~60°C, 0~90%RH
長度	110±2cm
重量	約 55g




補償調整孔



欠補償



過補償



正確補償